

A Lightbulb Worm?

A teardown of the Philips Hue.




Colin O'Flynn

(with special appearance by Eyal Ronen)



ABOUT ME

ChipWhisperer-Lite: A New Era of Hardware Security Research



Embedded security - is it an oxymoron? Learn the truth through a series of hands-on labs targeting computer and electrical engineers.

Created by

Colin O'Flynn



331 backers pledged \$88,535 CAD to help bring this project to life.



HACKS?

- ① Brick light-bulb by OTA firmware update.
- ② Move bulb onto unavailable network, or control bulb.
- ③ Hack into bridge, access ethernet.
- ④ Malware in bulbs to do #3?


Understanding

ZLL

BRIDGE



New Bulb



IMPORTANT NOTE

The following 7 slides are work that Colin O'Flynn HAS NOT contributed too.

If you are crediting the takeover attack, please reference the names in the slides, do not add me (Colin). I'm only talking about the teardown & some rooting stuff.

Taking full control of already installed smart lights from long distance



Eyal Ronen

Joint work with Prof. Adi Shamir and Mr. Achi-Or Weingarten

Weizmann Institute of Science

ZLL Touchlink mechanism

- Allows adding a light to the network
- Enforces a distance check mechanism (10 – 20 cm)

How can I connect multiple lamps to a Hue dimmer switch?


Date published 10/1/2015 - Last edited 7/4/2016

Power up the lamp you want to connect. Hold the Hue dimmer switch close to the lamp (<15cm) and press and hold the ON button until the LED on the front turns green (during this process lamp will blink several times).

Did this answer your question?

Yes

No



Our Attack

- Our attack
 - Take full control over Philips Hue lights from large distance
 - Fully autonomous attack kit
 - Of the shelf ZigBee evaluation board (TI cc2531 Zlight2)
 - USB power bank
 - War-driving and War-flying demonstrated
- Ethical disclosure
 - Full disclosure to Philips Lighting
 - Currently under internal investigation
 - Will allow more time before publishing the details



Zigbee War-driving




Work by Eyal Ronen et al (NOT Colin O'Flynn)

ZigBee War-flying



Work by Eyal Ronen et al (NOT Colin O'Flynn)

LIGHT BULB MALWARE OR (BRICKS)



LIGHT BULB MALWARE

- 1) ZLL key leaked. We know it's possible to "steal" bulbs.
- 2) Custom FW on bulbs could turn bulb into "bridge" that searches for & steals nearby bulbs.
- 3) If could cause other bulbs to perform OTA FW update → WORM

CHEAP

BULBS

A close-up photograph of a hand holding a white LED light bulb. The bulb has a standard E26 screw base. Printed on the lower part of the bulb's body is the following text:

800 Lumen
Hue white A19 9.5W 90mA
110-130Vac 50/60Hz
FCC ID: O3M9290011369X
IC: 10469A-1369X
Model: 9290011369

The background is a wooden surface with some blurred objects, including what appears to be a keyboard and some cables.


Hue white A19 9.5W 90mA
110-130Vac 50/60Hz
FCC ID: O3M9290011369X
IC: 10469A-1369X
Model: 9290011369




Heat sink

Antenna

Rubber?





Locked

```
[Log, Info, ConnectedLamp, MCUCR=0x00, LockBits=0xFC, LowFuse=0xF6, HighFuse=0x9A, ExtFuse=0xFE]
[Log, Info, ConnectedLamp, devsig=0x1EA803]
[Log, Info, S_DeviceInfo, Booting into normal mode...]
[Log, Info, S_DeviceInfo, DeviceId: Bulb_A19_DimmableWhite_v2]
[Log, Info, N_Security, LIB4.5.75]
[Log, Info, N_Security, KeyBitMask, 0x0012]
[Log, Info, ConnectedLamp, Platform version 0.41.0.1, package_ZigBee
117, package_BC_Stack 104, svn 26632]
[Log, Info, ConnectedLamp, Product version WhiteLamp-Atmel 5.38.1.15095, built
by LouvreZLL]
[Log, Info, A_Commissioning, Factory New at Ch: 11]
[TH, Ready, 0]
```

COM32 115200 bps, 8N1, no handshake

Settings

Clear

```
[00]YYYYYY
[Log,Info,ConnectedLamp,MCUCR=0x00,LockBits=0xFC,LowFuse=0xF6,HighFuse=0x9A,ExtFuse=0xFE]
[Log,Info,ConnectedLamp,devsig=0x1EA803]
[Log,Info,S_DeviceInfo,Booting into normal mode...]
[Log,Info,S_DeviceInfo,DeviceId: Bulb_A19_DimmableWhite_v2]
[Log,Info,N_Security,LIB4.5.75]
[Log,Info,N_Security,KeyBitMask,0x0012]
[Log,Info,ConnectedLamp,Platform version 0.41.0.1,package_ZigBee 117,package_BC_Stack 104,svn 26632]
[Log,Info,ConnectedLamp,Product version WhiteLamp-Atmel 5.38.1.15095,built by Louvre2LL]
[Log,Info,A_Commissioning,Factory New at Ch: 11]
[TH,Ready,0]
[Sys,test,1]
[SYS,Error,Incorrect format]
```

Working serial input too!

Tool: Atmel-ICE Device: ATmega2564RFR2 Interface: JTAG Device signature: 0x1EA803

Interface settings

Fuse Name	Value
BODLEVEL	1V8
OCDEN	
JTAGEN	☒
SPIEN	☒
WDTON	
EESAVE	
BOOTSZ	2048W_1F800
BOOTRST	☒
CKDIV8	
CKOUT	
CKSEL_SUT	TOSC_1KCK_4MS1

JTAG
test points
(see w.p.)

Tool: Atmel-ICE Device: ATmega2564RFR2 Interface: JTAG Device signature: 0x1EA803 Target Voltage: 3.3 V

Interface settings

Lock Bit	Value
LB	PROG_VER_DISABLED
BLB0	NO_LOCK
BLB1	NO_LOCK

See white-paper for JTAG pin-out connections.

BRIDGE

1.0

BRIDGE 1.0 HACKING

Bridge

Dumb hub

Run App



firmwareupdate_ethernet_bridge_around1206time.pcapng [Wireshark 1.8.0 (SVN Rev 43431 from /trunk-1.8)]


File Edit View Go Capture Analyze Statistics Telephony Tools Internals Help

Filter: Expression... Clear Apply Save

No.	Time	Source	Destination	Protocol	Length	Info
8500	1171.694544000	192.168.0.23	5.79.62.93	TCP	60	49640 > http [FIN, ACK] Seq=1623 Ack=873 win=1808 Len=0
8501	1171.694545000	192.168.0.23		DNS	79	standard query 0xaf13 A fds.cpp.philips.com
8502	1171.759431000		192.168.0.23	DNS	172	Standard query response 0xaf13 CNAME e4f.edgesuite.net CNAME a1049.g2.akamai.net A 173.237.125.64 A 173.237.125.64
8503	1171.759433000	192.168.0.23	173.237.125.64	TCP	60	49641 > http [SYN] Seq=0 win=2144 Len=0 MSS=536
8504	1171.769461000	173.237.125.64	192.168.0.23	TCP	64	http > 49641 [SYN, ACK] Seq=0 Ack=1 win=14600 Len=0 MSS=1460 [ETHERNET FRAME CHECK SEQUENCE INCORRECT]
8505	1171.769464000	192.168.0.23	173.237.125.64	TCP	60	49641 > http [ACK] Seq=1 Ack=1 win=2144 Len=0
8506	1171.769465000	192.168.0.23		HTTP	260	GET /firmware/BSB001/1030262/firmware_rel_cc2530_encrypted_stm32_encrypted_01030262_0012.fw HTTP/1.1
8507	1171.779553000	173.237.125.64	192.168.0.23	TCP	64	http > 49641 [ACK] Seq=1 Ack=207 win=15544 Len=0 [ETHERNET FRAME CHECK SEQUENCE INCORRECT]
8508	1171.808458000	5.79.62.93	192.168.0.23	TCP	64	http > 49640 [ACK] Seq=873 Ack=1624 win=3230 Len=0 [ETHERNET FRAME CHECK SEQUENCE INCORRECT]
8509	1171.972258000	173.237.125.64	192.168.0.23	TCP	590	[TCP segment of a reassembled PDU]

http://xxx/firmware/HUE0100/66013452/ConnectedLamp-Target_0012_13452_8D.sbl-ota

http://xxx/firmware/BSB001/1030262/firmware_rel_cc2530_encrypted_stm32_encrypted_01030262_0012.fw



CC2530 (Zigbee Chip)

RF Amplifier

Flash

Antenna

Ethernet

STM32F
Main Processor



Output from CC2530

```
[Log,Info,S_DeviceInfo,Booting into normal mode...]  
[Log,Info,S_DeviceInfo,DeviceId: IpBridge]  
[Log,Info,N_Security,LIB4.4.52]  
[Log,Info,N_Security,KeyBitMask,0x0012]  
[Log,Info,A_Bridge,Platform version 0.25.0,package_ZigBee 8720,package_Z_Stack  
8720,built by LouvreZLL]  
[Log,Info,A_Bridge,Product version 5.7.1,SmartBridge 11393,built by LouvreZLL]  
[Bridge,Version,5.7.1,SmartBridge 11393,built by LouvreZLL]  
[Bridge,GroupRange,0x5357,0x5367]  
[Log,Info,D_Led,dc 16]  
[Bridge,NetworkSettings,False,0xB163,26DF52A183D85889,11,0,S=0x0001]  
[Log,Info,A_Bridge,NwkAddr: 0x0001, Ch: 11, Pan: 0xB163, NwkUpdId: 0,  
ExtPanID:26:DF:52:A1:83:D8:58:89]  
[Log,Info,D_Led,dc 16]  
[TH,Ready,0]  
[Connection,A]  
[Connection,GetAddress,L=00:17:88:01:01:07:BF:FC,S=0x0001.0]  
[Bridge,StoreGroupRange,0]  
[Log,Info,N_ConnectionRouter,Startup network discovery...]
```

Input to CC2530

```
[Connection,GetAddress]  
[Bridge,StoreGroupRange,0x5357,0x5367]  
[Zcl,S,S=0x0002.11,6,0000000000]  
[Routing,ClearEntry,1]  
[Routing,SendMtoRR,True]  
[Zcl,S,S=0x0003.11,6,0001000000]  
[Routing,ClearEntry,2]  
[Routing,SendMtoRR,True]  
[Zcl,S,S=0x0002.11,6,0002000000]  
[Zcl,S,S=0x0003.11,6,0003000000]  
[Zcl,S,S=0x0002.11,6,0004000000]
```


BYPASS


ZLL

KEY?


```
[Zc],s,s=0x0004.11,6,001a000000,64]
[Zc],s,s=0x0004.11,8,001b000000,64]
[Zc],s,s=0x0004.11,768,001c000100004002400300040007000800,64]
[Zc],s,s=0x0004.11,25,190d05000b1000018c340042ae0100002b97098fac0320f2f31e3c8fd035a34097da5018feb50a2e8b40d3678aa57c866a47122020a3a86220a25c93,64]
[Zc],s,s=0x0004.11,25,190e05000b1000018c340042d90100002b2d3d4e5d25c0622af60856c62900d59f71b104541e744b3657ebc32286f3e635474145d3189f7deca60cd9,64]
[Zc],s,s=0x0003.11,6,001d000000,64]
[Zc],s,s=0x0004.11,25,190f05000b1000018c340042040200002b92c84eb5d02416e5153d8aa6a944b0dd7c9796547fa4f63793ea06c100f2c3293c87a425cd5279a8765d3d,64]
[Zc],s,s=0x0003.11,8,001e000000,64]
[Zc],s,s=0x0004.11,25,191005000b1000018c3400422f0200002ba0b3d5e50a0e550e48f25a6125d1aea4fca962453c7f718f05ec20c7875e799ae71b45cd7fc74b3e436094,64]
[Zc],s,s=0x0004.11,25,191105000b1000018c3400425a0200002b2956b4f0014e777aa0ba92c6cb8ed7ddd6d67c114bd4,96d5e03f65105ab62da87dac1c7d344e73ea4c901,64]
[Zc],s,s=0x0002.11,6,001f000000,64]
[Zc],s,s=0x0004.11,25,191205000b1000018c340042850200002be080f0a5152a9d4c0f7eed933a2a3262474106f57b2947d1c44121c326e1c8bfbaea0a925ed58e5a9290a1,64]
a691ef28438fee5be91305000b1000018c340042b00200002b965b229d29d5cf2c0f7eed933a2a3262474106f57b2947d1c44121c326e1c8bfbaea0a925ed58e5a9290a1,64]
[Zc],s,s=0x0004.11,25,191405000b1000018c340042db0200002ba14b4f7686df97989d0371c2c435f733cd9e9361bc90de747f9ec249c2fe86b90f2430595cc5ba87bde7c0,64]
[Routing,SendMtoRR,True]
[Zc],s,s=0x0004.11,25,191505000b1000018c340042060300002be67a19318a005a40204ccbc0126951982709f080f5806e33d478efd8dcda9e79303ad662ddcfa822316b03,64]
```

B3 D5 E5 0A	0E 55 0E 48	F2 5A 61 25	D1 AE A4 FC	°Öä	U P H ò Z a % Ñ @ c ũ
A9 62 45 3C	7F 71 8F 05	EC 20 C7 87	5E 79 9A 88	@ b E < 0 q	i Ç ð y š ç
1B 45 CD 7E	C7 4B 3E 43	00 94 23 5C	B4 F0 01 1B	< E í 0 Ç K > C ` "	) V ' ð r N
77 7A A0 BA	92 C6 CB 8E	D7 DD D6 D6	7C 11 4B D4	w z	° ʹ 𐀀 Ž > 𐀀 Ö ◀ K Ô
29 6D 5E 02	F0 51 05 AB	62 DA 87 DA	C1 C7 D3 44	9 m ^ ˆ ò Q	< b ũ 𐀀 Á Ç Ó D
E7 3E A4 C9	01 E0 80 F0	A5 15 2A 9D	4C 0F 7E ED	ç > c É r à	€ 𐀀 ˆ * L 0 ~ í
93 3A 2A 32	62 47 41 06	F5 7B 29 47	D1 C4 41 21	"	* 2 b G A - ð {) G Ñ Á Á !
C3 26 E1 C8	BF BA EA 0A	92 5E D5 8E	5A 92 90 A1	Ã & á È	¿ 𐀀 ' ^ Ö Ž Z ' i
96 5B 22 9D	29 D5 CF 2E	C8 1C 7E B2	7D 98 84 96	- [")	Ö İ . È ~ 2 } ~ „ -
DC 79 66 A9	7D 4E E7 41	B2 67 E4 CB	C1 C1 B2 BA	Ü y f @ }	N ç A ² g ä È Á Á ² °





TX1
RX1
DP
DC } Debug




RST

7

Serial Data During Boot load

② Data
③ Larger Delay during page erase
Each data block = 64 bytes



① Sign on

One page = 512 Bytes

A

B

Extracting Keys from Second Generation Zigbee Chips

Travis Goodspeed
1933 Black Oak Street
Jefferson City, TN, USA
travis@radiantmachines.com

ABSTRACT

First generation Zigbee chips were SPI slaves with no internal processing beyond cryptographic acceleration. Extracting a key was as simple as spying on the SPI transactions. The second generation chips, typified by the CC2430 from Texas Instruments and the EM250 from Ember, contain both a microcontroller and a radio, making the SPI sniffing attack all but irrelevant. Nevertheless, both chips are vulnerable to local key extraction. This paper describes techniques for doing so, focusing on the CC2430 as the EM250 has no protection against outside access. Recommendations are made for defending CC2430 firmware by using compiler directives to place sensitive information in flash memory, rather than in RAM. All Chipcon radios with 8051 cores released prior to the publication of this paper are expected to be vulnerable.

Keywords

Zigbee, CC2430, EM250, System on a Chip (SoC)

1. GENERATIONS

First generation Zigbee chips, such as the CC2420, were simply digital radios with SPI interfaces and a bit of hardware-accelerated cryptography. They could not run a Zigbee stack themselves, but rather relied upon an external microcon-

troller cores were added for convenience, not security, as will be explained below.

The third generation of chips will include more powerful microprocessors and—hopefully—a lot more security. The offering from Texas Instruments is the CC430 family, based upon the MSP430X2 processor. Ember will be using the Arm Cortex M3 in its EM300 series. These chips are out of scope for this paper, as they are not yet commercially available. Also, Freescale's line of radios have not yet been examined by the author, but they will be in the near future.

2. CONCERNING THE EM250

The Ember EM250 contains a 16-bit XAP2b microprocessor from Cambridge Consultants Ltd.[3] Debugging support is provided by that firm's proprietary SIF protocol, with hardware and software available only through Ember. SIF itself is a variant of JTAG.

While the datasheet and various piece of marketing literature claim "The EM250 employs a configurable memory protection scheme usually found on larger microcontrollers.", this refers not to a debugging fuse or bootloader password, but rather to protection from accidental self-corruption of memory. This is in the form of Application/System separation, allowing the EmberZNet stack to defend certain regions

Good Things

- ZLL master key not in regular SRAM

- Tried AES-128 CBC to decrypt boot loader image, where $\text{key} = \{\text{every possible 16-byte block}\}$

↳ No success, key not in SRAM?

```
..\\hue_lux_zll\\srandump\\bootloadersram_8192_firstframe.bin
0000 0000: 4A B5 7E CE 55 F0 B1 4E 49 57 4F B0 13 9E 7E B4 JÃ~?R- N IWO. .x~|
0000 0010: F3 6C D4 74 9E 3E B9 64 F5 4E E0 57 FE B3 BD 89 3lÊt>x>|ld SNóWm |çë
0000 0020: 3E D7 AF 25 B3 87 BF F7 4C 9F BF 7A 0F 9D 2B 7F >I>»|çj Lfjz.0+α
0000 0030: D5 B8 AF FC FF E4 C7 5D 6B 4F 48 9C 7C AC BE F3 ¹@»³ õã} kOHÉ!ÿÿ
0000 0040: 97 01 58 FF 00 00 FF FF 00 0E 07 AF FF 66 00 C7 ù.X .. -..° f.ã
0000 0050: F7 00 00 06 00 00 E9 09 FF 01 FA 80 76 03 00 80 .....ú. ..çv..ç
0000 0060: 7E 01 3C 05 07 FA 04 07 FA 04 B0 D2 F1 3B 00 6E ~.<..... Ë±;.n
0000 0070: 06 FF 00 FA 04 00 FA 04 00 5E 07 F6 0D 01 01 01 .....^..... ÷
0000 0080: 01 2A 00 01 01 00 66 CB 15 12 16 15 12 33 03 7E .*. ...fπ .....3.~
0000 0090: 80 87 74 01 F6 22 FC 87 DB 09 42 96 94 73 46 5C Ççt.÷"³ç ■.Bûösf\
0000 00A0: 16 FE 01 00 81 00 80 2A 00 01 01 00 66 CB 15 12 .■...ü.ç* .....fπ..
0000 00B0: 16 15 12 33 03 7E 00 2D 4A 27 D6 3C 49 6D B2 53 ...3.~ç- J' i<ImS
0000 00C0: 80 9E B7 CC 57 E1 95 A3 1A 18 80 54 E1 01 28 83 Ç>ã|AMôó ..çtø.Çã
0000 00D0: DA 24 B5 7E 4B AD 45 37 90 52 E5 85 98 10 13 F1 Çã~K+E7 ÉRôàÿ..±
0000 00E0: FD 86 E8 CD 30 32 C0 00 F6 88 00 00 00 00 00 00 ²ãp=02!! ÷
0000 00F0: 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 .....
0000 0100: 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 .....
0000 0110: 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 .....
0000 0120: 00 01 00 00 42 00 01 01 00 FA 0D 00 01 01 00 66 ....B... ..f
0000 0130: 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 .....
0000 0140: 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 .....
0000 0150: 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 .....
0000 0160: 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 .....
0000 0170: 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 .....
0000 0180: 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 .....
0000 0190: 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 .....
0000 01A0: 00 00 00 00 00 00 00 00 00 00 01 37 90 52 E5 .....7ÉRô
0000 01B0: 85 98 10 13 F1 FD 86 E8 CD 30 32 CA 66 00 01 00 àÿ..±²ãp =02!f...
```

```
..\\hue_lux_zll\\srandump\\bootloadersram_8192_firstpage.bin
0000 0000: 97 B9 94 8C 26 7B C1 53 31 42 DC A1 29 61 E4 AF 00i&<¹S 1B. i>aô»
0000 0010: FD B7 8F CF F7 F2 AF 94 6F FF 3E DC 69 F7 B4 76 ²A8x.=>ö o >mi |v
0000 0020: E3 DC B6 D9 BB B8 FA F8 E7 9D C1 EF FE EA FB D7 òã¹jü·° p0¹.ü¹i
0000 0030: AC 7F 53 4B 5E AB 58 8C DF 39 D7 93 1E 7E DE D6 3&SK~ÿxi ²ÿiô.~i i
0000 0040: CE 6A 58 FF 00 00 FF FF 00 EE 07 A7 FF 66 00 D7 ùjX .. -..° f.î
0000 0050: F7 00 00 06 00 00 E9 09 FF 00 F5 84 00 EB 00 52 .....ú. ..Sã.ù.R
0000 0060: 4B 06 DC 04 07 F5 04 07 F5 04 42 AD 7F 4F 00 6E K. ....S.. S.Bi△o.n
0000 0070: 06 4E 00 F5 04 00 F5 04 00 5E 07 E4 0D 01 01 01 .N.S...S. ..^..õ....~
0000 0080: 01 2A 00 01 01 00 66 CB 15 12 16 15 12 33 03 7E .*. ...fπ .....3.~
0000 0090: 80 87 74 01 F6 22 FC 87 DB 09 42 96 94 73 46 5C Ççt.÷"³ç p. Hó²ç>..
0000 00A0: 16 FE 01 00 81 00 80 FF FF FF FF FF FF FF FF FF FF ..ü.ç
0000 00B0: FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF .....
0000 00C0: FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF .....
0000 00D0: FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF .....
0000 00E0: FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF .....
0000 00F0: 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 .....õ.....
0000 0100: 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 .....
0000 0110: 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 .....
0000 0120: 00 01 00 00 42 00 01 01 00 FA 0D 00 01 01 00 66 ....B... ..f
0000 0130: 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 .....
0000 0140: 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 .....
0000 0150: 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 .....
0000 0160: 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 .....
0000 0170: 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 .....
0000 0180: 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 .....
0000 0190: 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 .....
0000 01A0: 00 00 00 00 00 00 00 00 00 00 01 37 90 52 E5 .....7ÉRô
0000 01B0: 85 98 10 13 F1 FD 86 E8 CD 30 32 CA 66 00 00 00 àÿ..±²ãp =02!f...
```

Rx
Buffer
RxCRC

Tx Buffer

RxCRC

Page#

??
..

TX BUFFER ATTACK

```
for(uint8 i=0; i < data-to-send, i++) {  
    uart_write(tx_buf[i]);  
}
```

Tx Buffer

90:	80	87	74	01	F6	22	FC	87	DB	09	42	96
A0:	16	FF	01	00	81	00	80	2A	00	01	01	00
B0:	16	15	12	33	03	7E	80	2D	4A	27	D6	3C
C0:	80	AE	B7	CC	57	11	95	A3	1A	1A	80	54
D0:	00	04	05	7E	40	00	4E	27	00	52	FE	05

TX BUFFER ATTACK


```
for(uint8 i=0; i < data-to-send, i++) {  
    uart_write(tx_buf[i]);  
}
```

Glitch Attack!

Tx Buffer

90:	80	87	74	01	F6	22	FC	87	DB	09	42	96
A0:	16	FE	01	00	81	00	80	2A	00	01	01	00
B0:	16	15	12	33	03	7E	80	2D	4A	27	D6	3C
C0:	80	FE	B7	CC	57	11	95	A3	1A	1A	80	54
D0:	00	04	05	7E	40	00	4E	27	00	50	FE	05


Rx BUF




Custom PCB

CC2530 from Bridge


Clock Glitching







**Original
Clock**

7.37 MHz



**Width = 10%
Offset = +15%**

**Clock XORd
with Glitch**



1 2.00 V R_W 2 2.00 V R_W Z 200 μ s 250MS/s B1 Tx Data
1.50000ms 10M points

Bus Search events found: 0

3 Apr 2016
15:38:03

Search
On



Search Type
Bus

Source Bus
B1 (RS-232)

Search For
Tx Data

Data
4A 27h





1

2.00 V

B_W

2

2.00 V

B_W

Z 200µs

T 25.00 %

125MS/s

5M points

B1

Tx Data

3 Apr 2016

17:38:22

2

B1

(Tx)

(Rx)

Zoom Factor: 20 X

2

B1

(Tx)

(Rx)

0000	00D0:	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF		
0000	00E0:	FF	FF	FF	FF	FF	FF	FF	00	E4	00	00	00	00	00	00	00	00		6
0000	00F0:	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00		
0000	0100:	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00		
0000	0110:	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00		
0000	0120:	00	01	00	00	42	00	01	22	00	FA	0D	00	01	01	00	66		B	f
0000	0130:	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00			
0000	0140:	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00			
0000	0150:	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00			
0000	0160:	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00			
0000	0170:	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00			
0000	0180:	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00			
0000	0190:	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00			
0000	01A0:	00	00	00	00	00	00	00	00	00	00	00	01	37	90	52	E5		7ÉRõ	
0000	01B0:	85	98	10	13	F1	FD	86	E8	CD	30	32	CA	66	00	00	00		àü...±²&P	=021f...

00 00 00 00 00 00 00 00 00 00 01 61 00 42 00 01 03 00 FA 0D

Targetted page 3

1

2.00 V

B_W

2

2.00 V

B_W

Z 200µs

T 25.00 %

125MS/s

5M points

B1

Tx Data

3 Apr 2016

17:38:29

Appears section of SRAM
is erased after use.


↳ This is good practice!

↳ May be possible with more
glitches.

Glitch Attacks To Firmware



- Appears we can use glitching to dump SRAM.
- Careful timing required to get decrypted data.

R.I.P.




BRIDGE

2.0



HACKING
TOOLS






```
[ 0.600000] io scheduler noop registered
[ 0.600000] io scheduler deadline registered (default)
[ 0.610000] Serial: 8250/16550 driver, 1 ports, IRQ sharing disabled
[ 0.630000] serial8250.0: ttyS0 at MMIO 0x18020000 (irq = 11, base_
[ 0.640000] console [ttyS0] enabled
[ 0.640000] console [ttyS0] enabled
[ 0.650000] bootconsole [early0] disabled
[ 0.650000] bootconsole [early0] disabled
[ 0.660000] m25p80 spi0.0: found gd25d40, expected m25p80
[ 0.670000] m25p80 spi0.0: gd25d40 (512 Kbytes)
[ 0.670000] 4 cmdlinepart partitions found on MTD device spi0.0
[ 0.680000] Creating 4 MTD partitions on "spi0.0":
[ 0.680000] 0x000000000000-0x0000000040000 : "u-boot"
[ 0.690000] 0x0000000040000-0x0000000060000 : "u-boot-env"
[ 0.690000] 0x0000000060000-0x0000000070000 : "reserved"
[ 0.700000] 0x0000000070000-0x0000000080000 : "art"
[ 0.710000] nand: device found, Manufacturer ID: 0xc8, Chip ID: 0xb
[ 0.720000] nand: Giga Device GD5F1GQ4U 1G 3.3V 8-bit
[ 0.730000] nand: 128MiB, SLC, page size: 2048, OOB size: 128
[ 0.730000] Scanning device for bad blocks
[ 0.900000] Bad eraseblock 768 at 0x000006000000
[ 0.900000] Bad eraseblock 776 at 0x000006100000
```

<https://www.youtube.com/watch?v=hi2D2MnwiGM>

Or: <http://www.oflynn.com>



<https://www.youtube.com/watch?v=hi2D2MnwiGM>
Or: <http://www.oflynn.com>

eth1: 00:17:88:24:15:8e

athrs27_phy_setup ATHR_PHY_CONTROL 0 :1000

athrs27_phy_setup ATHR_PHY_SPEC_STAUS 0 :10

athrs27_phy_setup ATHR_PHY_CONTROL 1 :1000

athrs27_phy_setup ATHR_PHY_SPEC_STAUS 1 :10

athrs27_phy_setup ATHR_PHY_CONTROL 2 :1000

athrs27_phy_setup ATHR_PHY_SPEC_STAUS 2 :10

athrs27_phy_setup ATHR_PHY_CONTROL 3 :1000

athrs27_phy_setup ATHR_PHY_SPEC_STAUS 3 :10

eth1 up

eth0, eth1

Qualcomm Atheros SPI NAND Driver, Version 0.1 (c) 201

ath_spi_nand_ecc: Couldn't enable internal ECC

Setting 0x181162c0 to 0x4b97a100

Hit any key to stop autoboot: 0

** Device 0 not available

ath> 

Use "mkpasswd"

```
ath> setenv bootdelay 3  
ath> printenv security
```

*****COPY THE DEFAULT VALUE THAT WAS PRINTED & SAVE THIS SOMEWHERE*****

```
ath> setenv security '$5$wbgtEC1iF$ugIfQUoE7SNg4mplDI/7xdfLC7jXoMAkupeMsm10hY9'  
ath> printenv security  
security=$5$wbgtEC1iF$ugIfQUoE7SNg4mplDI/7xdfLC7jXoMAkupeMsm10hY9  
ath> saveenv  
ath> reset
```

<https://www.youtube.com/watch?v=hi2D2MnwiGM>


<http://colinoflynn.com/?p=706>

- Master binary seems to “do it all” (webserver, parsing requests, etc.)
at `/usr/sbin/ipbridge`
- FW Update routine at `/usr/sbin/swupdate`
 - References AES-CBC-256 decryption routine, which references encryption key
at `/home/swupdate/certs/enc.k`
 - Two different bridges used same AES key (not really a big deal, as we already have unencrypted binaries since we have root).






4




4




① — ④ = AES-128?
would explain 64 bytes.

Previous slide: power signature of first 64-byte block sent (sign-on info?).
This slide: Power signature for remaining 64-byte blocks (delay varies).


- ▶ SAM D20 Xplained Pro (109)
- ▶ SAM D21 Xplained Pro (232)
 - 8MHz Oscillator Calibration Application - SAM D21 Xplained Pro
 - ADP example application - SAM D21 Xplained Pro
 - AES Software Library Demo - SAM D21 Xplained Pro
 - Alert Notification Client Application - SAM D21 Xplained Pro



ECB



CBC



CTR


64 BYTE DECRYPTION


BR30

DOWN LIGHT


CC 2530 Based









Firmware Update Hacking




Using Salae Pro-16

↳ Capture 8MHz SPI Traffic




Page Erase



Pass #1

Pass #2




First block sent

000780:	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
000790:	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0007A0:	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0007B0:	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	
0007C0:	2A	00	01	00	00	66	52	14	10	02	17	30	39	03	EF	40	*....fR....09..@
0007D0:	2E	37	0B	25	EC	C0	47	65	CB	E1	1E	0E	74	F7	A1	14	.7.%..Ge....t...
0007E0:	EE	6B	58	B5	2F	F3	0D	83	68	12	67	71	4C	7A	75	20	.kX./...h.gqLzu
0007F0:	4D	08	E0	74	95	54	CE	AB	23	72	2B	80	AB	46	46	CD	M..t.T..#r+..FF.
000800:	77	CF	AC	2E	8C	58	9E	75	8C	1D	77	43	D5	A2	28	5C	w....X.u..wC..(\
000810:	4E	94	CC	F9	C8	C5	5B	62	E7	09	8B	E3	6A	3A	0C	07	N.....[b....j:..
000820:	86	27	80	7A	76	91	90	AA	1E	8F	40	FD	35	96	CC	C0	.'.zu.....@.5...
000830:	BF	53	2D	F0	88	7E	28	ED	F3	B7	96	AF	65	8C	8A	1D	.S-..~(.....e...
000840:	D6	8B	07	49	EE	8C	B7	49	54	D9	D9	62	94	62	65	0C	...I...IT..b.be.
000850:	99	E4	B8	4A	CE	17	26	28	A8	FF	F3	4C	48	45	B0	A0	...J..&(...LHE..
000860:	2E	29	3D	2A	4E	1D	40	42	C3	8A	9D	E0	D6	6E	47	98	.)=*N.@B.....nG.
000870:	D3	42	47	CF	29	EC	BC	88	CB	FB	35	15	CD	DB	8A	FE	.BG.).....5.....

SRAM Dump

↳ DURING BOOTLOAD

That block from previous page.



Reset (entering debug)

Block

First 16 bytes of block

SRAL

0309

IL7
Signature?

Address of SPI

SECURITY CONCLUSIONS

① Huge risk to Philips if worm designed.

② Good security practices in place to prevent this:

- Encrypted FW
- Keep Keys out of SRAM
- Signed FW (Linux only)
- Clear memory when done.

③ Trade-offs May cause future problems:

- Same key decrypts FW updates across many devices.
- ZLL master key leak opens up lamp-stealing.
- Huge Linux binary does a lot, vulns?
- See White Paper for more!

Eyal Ronen

<http://www.wisdom.weizmann.ac.il/~eyalro/>

<http://www.wisdom.weizmann.ac.il/~eyalro/PhilipsHueTakeOver/>
@eyalr0

eyal.ronen@weizmann.ac.il

Colin O'Flynn

@colinoflynn

oflynn.com

newae.com

coflynn@newae.com

Also read the
w.p. for details.

<http://colinoflynn.com/2016/08/philips-hue-r-e-whitepaper-from-black-hat-2016/>